

# FREE

# DARK

## style

### Specifications

#### 1. printing

- Change printer/copier settings to "Heavy / Card Stock" and use bypass
- Print only onto the coated side (blank side)
- In order to get the transfer the right way round, print the motif in positive mode on the paper

#### 2. preparation the transfer

- Cut out the image with a small margin
- Release the backing paper off the print carrier and place image side face up onto the fabric which must be wrinkle free and pre-ironed.

#### 3. transfer

- Heat the transfer press to 180°C/355°F and adjust medium to high pressure.
- Enclosed you will find a new release paper which is a special protection paper for the transfer. The special protection paper is both sides coated. Use the glossy side for transferring.
- Now place the special release paper onto the image and press 25-30 sec.
- Take the fabric off the heat press. Finally, when the image is cooled down peel off the protection paper!

#### 4. cleaning the special protection paper

- The special protection paper can be used for several times.
- It can be cleaned by pressing it onto normal paper for 5-10 sec. and peel cold.

#### 5. washing

- Max. wash 40° C
- Turn the garment inside out
- Do not bleach
- Do not use a tumble-dryer
- Do not iron the transferred motif directly. If garment needs ironing, iron the back side from the fabric.



[www.geadata.hr](http://www.geadata.hr)

Uvoznik i distributer za Premium transfer:  
Gea data d.o.o. na trgovinu uvoz i izvoz  
Vrhovec 20/II 10 000 Zagreb, HR  
e.mail: [geadata@gmail.com](mailto:geadata@gmail.com)  
[www.geadata.hr](http://www.geadata.hr)